

OUT54465

034 NOV 15 22 10Z

P 162057Z  
FM NPIC WASHDC *Multi*  
TO RUCSC/SAC OFFUTT AFB OMAHA NEB  
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
RUCVAA/2D RTS BARKSDALE AFB LA  
RUEAHQ/DIA WASHDC  
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD  
RUEPIA/CIA WASHDC  
RUWBN/15TH AF MARCH AFB RIVERSIDE CALIF  
RUWGAA/2AF BARKSDALE AFB LA  
BT  
S E C R E T CITE NPIC 3295.

Declassification Review by NGA/DoD

OPS FILES

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-15 WAS USED IN MISSION 3966 FLOWN ON 13 NOVEMBER  
1964. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: A PLUS DENSITY LINE IS PRESENT PARALLEL TO AND  
3.3" FROM THE INBOARD EDGE IN THE FIRST 100 FRAMES OF THE MISSION.  
DENDRITIC STATIC TRACES OCCUR OCCASIONALLY ALONG THE INBOARD EDGE.  
A HEAT SPLICE IS LOCATED IN FRAME 1291 AND A MANUFACTURER'S SPLICE  
IN FRAME 1483.

C. 9L SIDE: THE OUTBOARD EDGE OF THE FILM IS SLIGHTLY  
WRINKLED ON FRAMES 890 THROUGH 916. A HEAT SPLICE IS MADE IN FRAME  
1267 AND A MANUFACTURER'S SPLICE IN FRAME 2430 WITH ASSOCIATED  
STATIC TRACES AND FOG PRESENT ON FRAMES 2425 THROUGH 2435.

D. BOTH SIDES: EDGE STATIC AND EDGE FOG ARE PRESENT INTER-  
MITTENTLY ALONG THE INBOARD AND OUTBOARD EDGES OF BOTH 9L AND 9R.  
ROLLER CHATTER APPEARS ALONG THE INBOARD EDGE INTERMITTENTLY  
THROUGHOUT. THE FRAMES ARE TITLED FROM 0001 THROUGH 2530.

1

E. NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES WERE OBSERVED ON THIS MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 15 PERCENT OF THE MISSION.

/END OF MESSAGE/

1